

NTSB National Transportation Safety Board

Office of Aviation Safety

Flight Crew Performance: Operational Factors

Captain David Tew Operations Group Chairman



- Captain required to conduct a taxi briefing
 - Airport diagram
 - Extra care crossing runways
- Abbreviated briefing
- First flight as a crew



- First officer briefed "taxi to runway 22 via taxiway alpha"
 - Runway end lights out
 - "Lights out all over the place"
- Did not include crossing runway 26



- Controller issued standard clearance to runway 22
- Consistent with two earlier flights



- Chart and taxiway identifications
 - Taxiway A5 redesignated A
 - Chart depicted paved surfaces accurately
- Crew did not receive local NOTAM
- Construction not on ATIS broadcast
- Closed taxiway had barricades



Taxi Activities


- First officer performed before takeoff checks
- 40 seconds of nonpertinent conversation
 - Noncompliance with sterile cockpit regulations



Taxi Activities

- Stopped at runway 26 hold short line
- Advised controller that flight ready to depart
- Time was available for flight crew to confirm airplane's location





Safety Recommendation

- Recommendation A-06-83
 - Require cross-check and location confirmation
- FAA issued guidance
- Cross-checking and location confirmation should be required



Takeoff Actions

- Crew noticed absence of runway lights
- No guidance for operations on unlighted runways
- Recommendation to establish relevant guidance
- FAA complied



Takeoff Actions

- V1-rotate call out followed by "whoa"
- Callout made 11 knots below planned rotation speed



Takeoff Actions

- End of runway indicated hazardous situation
- First officer pulled control column full aft
- Beyond point at which takeoff could be aborted





NTSB